

Supporting List

1. Motherboard Water Blocks

| Manufacture | Socket | Chipset | Model | Northbridge | Southbridge | Mosfet I/O | Mosfet UP |
|-------------|-----------|---------|---------------|-------------|-------------|---------------|---------------|
| ASUS | Intel 775 | P965 | COMMANDO | NS-10 | NS-10 | MF-10 + MFP-1 | none |
| | | | P5B Deluxe | NS-10 | NS-10 | MF-10 + MFP-1 | none |
| | | 975X | P5W DH Deluxe | NS-10 | NS-10 | MF-10 + MFP-1 | none |
| | | | P5WD2 | NS-10 | NS-10 | not support | none |
| | | P35 | P5K/EPU | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5K PRO | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5K-E | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5K Premium | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5K3 Deluxe | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5K Deluxe | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5K-E WIFI-AP | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5K WS | NS-10 | NS-10 | MF-10 + MFP-1 | none |
| | | | P5K64 WS | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | Blitz Formula | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |



GBU INTERNATIONAL CORP.

E-mail: larkooler@gbuintl.biz Website: www.gbuintl.biz

| | | | | | | | |
|--|--|-----|-----------------------|-------|-------|---------------|---------------|
| | | | Blitz Extreme | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | G35 | P5E-VM HDMI | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | P43 | P5QL-E | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | P45 | P5QC | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5Q Premium | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5Q WS | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5Q Deluxe Wifi-AP | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5Q PRO | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5Q-E | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5Q Deluxe | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5Q | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | Maximus II Formula | NS-10 | check | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | X38 | P5E64 WS Professional | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5E3 WS Professional | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5E WS Professional | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | Maximus Formula | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5E3 Deluxe | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |



GBU INTERNATIONAL CORP.

E-mail: larkooler@gbuintl.biz Website: www.gbuintl.biz

| | | | | | | | |
|--|-------------|-----|-----------------------|-------|-------------|---------------|---------------|
| | | | P5E3 Premium | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5E | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5E3 Deluxe Wifi-AP | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | Maximus Extreme | NS-10 | not support | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | Maximus Formula SP | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | X48 | P5E3 Premium Wifi-AP | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5E64 ES Evolution | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | RAMPAGE Formula | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | RAMPAGE Extreme | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | nForce 4 | | P5ND2 Deluxe | NS-10 | NS-10 | not support | not support |
| | nForce 650i | | P5N-E SLI | NS-10 | NS-10 | not support | not support |
| | nForce 680i | | STRIKER II Extreme | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5N32-E SLI | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | nForce 780i | | STRIKER II Formula | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | P5N-T Deluxe | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | nForce 790i | | P5N64 WS Professional | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | | | STRIKER II NSE | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |



GBU INTERNATIONAL CORP.

E-mail: larkooler@gbuintl.biz Website: www.gbuintl.biz

| | | | | | | | |
|----------|------------|----------------|---------------------|-------|-------|---------------|---------------|
| | | | STRIKER II Extreme | NS-10 | NS-10 | MF-10 + MFP-1 | MF-10 + MFP-1 |
| | Intel 1366 | X58 | P6T Deluxe | NS-10 | NS-10 | contact | contact |
| | | | P6T Deluxe OC Palm | NS-10 | NS-10 | contact | contact |
| | | | P6T WS Professional | NS-10 | NS-10 | contact | contact |
| | | | RAMPAGE II Extreme | NS-10 | NS-10 | contact | contact |
| | AMD 939 | nForce 4 | A8N32-SLI Deluxe | NS-10 | NS-10 | MF-10 + MFP-1 | none |
| | | nForce 4 SLI | A8N SLI Deluxe | NS-10 | NS-10 | MF-10 + MFP-1 | none |
| | AMD 940 | nForce 590 SLI | M2-Crosshair | NS-10 | NS-10 | contact | contact |
| | | | M2N32 SLI Deluxe | NS-10 | NS-10 | contact | MF-10 + MFP-1 |
| | | AMD 790FX | M3A32-MVP Deluxe | NS-10 | NS-10 | contact | none |
| GIGABYTE | Intel 775 | P965 | GA-965GM-S2 | NS-10 | NS-10 | none | none |
| | | | GA-965P-DQ6 | NS-10 | NS-10 | contact | contact |
| | | | GA-965P-DS3 | NS-10 | NS-10 | none | none |
| | | | GA-965P-DS3P | NS-10 | NS-10 | contact | contact |
| | | | GA-965P-DS4 | NS-10 | NS-10 | contact | contact |
| | | P35 | GA-P35C-S3 | NS-10 | NS-10 | none | none |
| | | | GA-P35C-DS3 | NS-10 | NS-10 | none | none |



GBU INTERNATIONAL CORP.

E-mail: larkooler@gbuintl.biz Website: www.gbuintl.biz

| | | | | | | | |
|--|--|--|---------------|-------|-------|-------|-------|
| | | | GA-P35C-DS3R | NS-10 | NS-10 | none | none |
| | | | GA-P35-DQ6 | NS-10 | NS-10 | MF-10 | MF-10 |
| | | | GA-P35-DS3 | NS-10 | NS-10 | none | none |
| | | | GA-P35-DS3L | NS-10 | NS-10 | none | none |
| | | | GA-P35-DS3R | NS-10 | NS-10 | none | none |
| | | | GA-P35-DS3P | NS-10 | NS-10 | MF-10 | MF-10 |
| | | | GA-P35-DS4 | NS-10 | NS-10 | MF-10 | MF-10 |
| | | | GA-P35-S3 | NS-10 | NS-10 | none | none |
| | | | GA-P35-S3L | NS-10 | NS-10 | none | none |
| | | | GA-P35T-DS4 | NS-10 | NS-10 | MF-10 | MF-10 |
| | | | GA-P35T-DQ6 | NS-10 | NS-10 | MF-10 | MF-10 |
| | | | GA-EP35C-DS3R | NS-10 | NS-10 | none | none |
| | | | GA-EP35-DS3 | NS-10 | NS-10 | none | none |
| | | | GA-EP35-DS3L | NS-10 | NS-10 | none | none |
| | | | GA-EP35-DS3R | NS-10 | NS-10 | none | none |
| | | | GA-EP35-DS3P | NS-10 | NS-10 | MF-10 | MF-10 |
| | | | GA-EP35-DS4 | NS-10 | NS-10 | MF-10 | MF-10 |



GBU INTERNATIONAL CORP.

E-mail: larkooler@gbuintl.biz Website: www.gbuintl.biz

| | | | | | | |
|--|-----|-----------------|-------|-------|-------------|-------------|
| | P43 | GA-EP43-DS3 | NS-10 | NS-10 | none | none |
| | | GA-EP43-DS3L | NS-10 | NS-10 | none | none |
| | | GA-EP43-DS3R | NS-10 | NS-10 | none | none |
| | | GA-EP43-S3L | NS-10 | NS-10 | none | none |
| | P45 | GA-EP45C-DS3 | NS-10 | NS-10 | none | none |
| | | GA-EP45C-DS3R | NS-10 | NS-10 | none | none |
| | | GA-EP45-DS3 | NS-10 | NS-10 | none | none |
| | | GA-EP45-DS3L | NS-10 | NS-10 | none | none |
| | | GA-EP45-DS3R | NS-10 | NS-10 | none | none |
| | | GA-EP45-DS3P | NS-10 | NS-10 | MF-10 | MF-10 |
| | | GA-EP45-UD3R | NS-10 | NS-10 | MF-10+MFP-1 | MF-10+MFP-1 |
| | | GA-EP45-UD3P | NS-10 | NS-10 | MF-10+MFP-1 | MF-10+MFP-1 |
| | | GA-EP45-DS4 | NS-10 | NS-10 | MF-10 | MF-10 |
| | | GA-EP45-DS4P | NS-10 | NS-10 | MF-10 | MF-10 |
| | | GA-EP45-DS5 | NS-10 | NS-10 | MF-10 | MF-10 |
| | | GA-EP45-DQ6 | NS-10 | NS-10 | MF-10 | MF-10 |
| | | GA-EP45-Extreme | NS-10 | NS-10 | MF-10 | MF-10 |



| | | | | | | | |
|--|--------|------------|------------------|----------------|-------|-------------|-------------|
| | | | GA-EP45T-DS3 | NS-10 | NS-10 | none | none |
| | | | GA-EP45T-DS3R | NS-10 | NS-10 | none | none |
| | | | GA-EP45T-Extreme | NS-10 | NS-10 | MF-10 | MF-10 |
| | | X38 | GA-X38-DQ6 | NS-10 | NS-10 | contact | none |
| | | X48 | GA-X48-DS4 | NS-10 | NS-10 | contact | none |
| | | | GA-X48-DS5 | NS-10 | NS-10 | contact | none |
| | | | GA-X48-DQ6 | NS-10 | NS-10 | contact | none |
| | | | GA-X48T-DQ6 | NS-10 | NS-10 | contact | none |
| | | X58 | GA-EX58-UD3R | NS-10 | NS-10 | contact | MF-10+MFP-1 |
| | | | GA-EX58-UD3R-SLI | NS-10 | NS-10 | contact | MF-10+MFP-1 |
| | | | GA-EX58-DS4 | NS-10 | NS-10 | MF-10+MFP-1 | MF-10+MFP-1 |
| | | | GA-EX58-UD4 | NS-10 | NS-10 | MF-10+MFP-1 | MF-10+MFP-1 |
| | | | GA-EX58-UD4P | NS-10 | NS-10 | MF-10 | MF-10 |
| | | | GA-EX58-UD5 | NS-10 | NS-10 | MF-10 | MF-10 |
| | | | GA-EX58-Extreme | NS-10 | NS-10 | check | MF-10 |
| | AMD940 | nForce 550 | GA-M55S-S3 | NS-10 | none | contact | none |
| | | | AMD 790FX | GA-MA790FX-DS5 | NS-10 | NS-10 | contact |



2. VGA Water Block

| | |
|--------|--|
| nVidia | FX 5900 5950 Series 6600 6800 Series, 7300 7600 7800 7900 Series, 8500 8600 8800 Series, 9600 9800 Series, GTX250 GTX260 GTX280 Series |
| ATI | X1600 X1900 X1950 Series, HD2600 HD2900 Series, HD3850 HD3870 Series, HD4650 HD4670 HD4830 HD4850 HD4870 HD4890 Series |



GBU INTERNATIONAL CORP.

E-mail: larkooler@gbuintl.biz Website: www.gbuintl.biz